


Rotary trim machine

Shuttle trim machine

Trim dies for aluminium castings

Trim dies for iron castings



For large parts finishing

- Three station machines for trimming the parting line
- Four station machines for multidirectional trimming of parting line and core prints
- With rates up to 500 cycles per hour, they can absorb, with a small staff, the production of automatic molding lines.
- Scrap conveyor
- Gantry for tool change
- Link to testing lin

